

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1. Name of the Officer SINI. P
2. Name of the School K.P.M MODEL SCHOOL
3. Location with name of Education District/ Sub. District Mayyanad, Kollam.
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.
RCC Building
75 x 9.15 x 11 m
41 x 9.15 x 11 m } 3 storey
5. Period for which the certificate is issued 2018-19
6. Nature of defects, if any
 - a) Foundation and basement
 - b) Superstructure
 - c) Doors and Windows
 - d) Wood work wrought and put up
 - e) Roof
 - f) Flooring
 - g) Miscellaneous (Cracks, etc.)Nil
7. Any major defects noticed which will render the building unsafe in any manner NA
8. Whether maintenance works have been done properly Yes
9. Whether the structure is sound or not for conducting classes The structure is sound enough under normal wind and weather conditions

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

certified that the school building was inspected by me on 01.08.2018 and found to be fit / ~~unfit~~ to conduct classes, for the period 2018-19 for the reasons stated above.

Place: Mayyanad
Date: 01.08.2018




Assistant Engineer
L.S.G.D Section
Mayyanad Grama Panchayat
Assistant Engineer